

| TELEOPTICS REPAIR PRICE 2010 | | | | |
|--|----------------|----------------|----------------|----------------|
| MODEL NAME | CLASS A | CLASS B | CLASS C | CLASS D |
| PH10x, J/PH12x, YH13x KRS/KTS | 95 | 205 | 390 | 575 |
| J/PH15, YJ/YH17, YH14, YH16 KRS/KTS | 120 | 235 | 455 | 695 |
| YJ/YH18x, 19x KRS/KTS | 150 | 270 | 480 | 800 |
| YJ18/YH18x, 19x IRS/ITS | 165 | 300 | 510 | 895 |
| KH19x6.7 KAS-AF | 150 | 270 | 480 | 800 |
| J/PH15x IRS | 165 | 300 | 510 | 900 |
| J/PH13x, J13ax IRS, YJ/YH12x KRS | 185 | 360 | 580 | 1055 |
| J13AX IRS | 185 | 365 | 650 | 1050 |
| J/PH8x KRS, YJ/YH12x IRS | 200 | 380 | 600 | 1070 |
| J/PH8x IRS | 215 | 405 | 800 | 1485 |
| J9ax WRS | 320 | 560 | 1055 | 2090 |
| J11ax IRS | 325 | 555 | 1050 | 2090 |
| J11ax WRS | 355 | 605 | 1120 | 2145 |
| J/PH14ax, 15ax, 16ax, IRS/VRS | 235 | 440 | 850 | 1600 |
| J15ax, J16ax, WRS | 285 | 495 | 910 | 1750 |
| J/PH18x IRS | 230 | 415 | 810 | 1520 |
| J/H20ax, 17ax, 21ax, 22ex IRS/VRS J13a/J14a, VAP | 325 | 555 | 1020 | 2100 |
| J17ax, 20ax, 21ax, 22ex WRS | 355 | 605 | 1120 | 2145 |
| J16AX/H16AX IRS/WIRS | 315 | 535 | 750 | 1680 |
| J21AX/H21AX IRS/WIRS | 335 | 570 | 950 | 1680 |
| NEW HIGH DEFINITION SERIES | | | | |
| HJ9x5.5, HJ11x4.7 IRS/IAS | 355 | 605 | 1120 | 2145 |
| HJ15x8 IRS/IAS | 325 | 605 | 1050 | 2090 |
| HJ16x8 IRS/IAS | 345 | 640 | 1150 | 2250 |
| HJ17x7.7, HJ18x7.8, HJ21x7.8, HJ22x7.6 IRS/IAS | 385 | 680 | 1230 | 2360 |
| HJ21x7.5 IRS/IAS | 395 | 700 | 1350 | 2500 |

For more information contact us:
 13004, Mitchwin Rd. , Dallas, Texas 75234
 Phone: 972-241-6610 • Fax 972-241-1334